

Matter No.: 12816-092001 Applicant(s): Heinrich Schenk TRANSMISSION SYSTEM

1/3





Insertion loss

Fig. 2

2/3




Fig. 3A




Fig. 38




Fig. 4

Matter No.: 12816-092001 Applicant(s): Heinrich Schenk TRANSMISSION SYSTEM

3/3




Fig. 5




Fig. 6